


## Material Take Off Interface Flow



MTO Upload

Load file

Check data  Delete invalid

Get last MTO: B10001

Export path: G:\   MTO File

File name:   P&M File

Last used part nr. B10001-0000688

Save

Drag a column header here to group by that column

Project	Drawing	Position	Rev.no.	Disc.	Error	Valid	Part No	Ownr	Qty	Description	Tagnr	Client code 1	Spec1
▶ B10001	RD-CSDA-	1	0	○		<input checked="" type="checkbox"/>	B10001-0000348	C	1	LBT 850 T LIFEBOAT	79D-Z-27101		
B10001	RD-CSDA-	1	0	○		<input checked="" type="checkbox"/>	B10001-0000350	C	1	NRD 10500 H DAVIT	PART OF: 79D-Z-27101		
B10001	RD-CSDA-	1	0	○		<input checked="" type="checkbox"/>	B10001-0000349	C	1	ENGINE HEATER	PART OF: 79D-Z-27101		
B10001	RD-CSDA-	1	0	○		<input checked="" type="checkbox"/>	B10001-0000346	C	1	SOFT STARTER	PART OF: 79D-Z-27101		
B10001	RD-CSDA-	1	0	○		<input checked="" type="checkbox"/>	B10001-0000347	C	1	42V TRANSFORMER	PART OF: 79D-Z-27101		

Record 1 of 5

**Check data has been executed**